




DATA NO. \_\_\_\_\_ MAP NO. \_\_\_\_\_ BLK. NO. \_\_\_\_\_ LOT NO. \_\_\_\_\_ FIELD BOOK \_\_\_\_\_ LAND VALUE \_\_\_\_\_ BLDG. VALUE \_\_\_\_\_ PURCH. PRICE \_\_\_\_\_ DATE \_\_\_\_\_  
 OCCUPANCY \_\_\_\_\_ TYPE & CONST. \_\_\_\_\_ SIZE \_\_\_\_\_ AREA \_\_\_\_\_ GRADE \_\_\_\_\_ AGE \_\_\_\_\_ EFF. AGE \_\_\_\_\_ COND. \_\_\_\_\_ REPL. VALUE \_\_\_\_\_ PHY. DEPR. \_\_\_\_\_ PHY. VALUE \_\_\_\_\_ FUNCT. DEPR. \_\_\_\_\_ LOC. ADJ. \_\_\_\_\_ ACT. VAL. \_\_\_\_\_  
 12-1 HBE 42x30 1712 31 P32 65 AVE

FOUNDATION \_\_\_\_\_ INTERIOR FINISH \_\_\_\_\_ OUTBUILDINGS 1 2 3 \_\_\_\_\_  
 CONG. OR BRICK \_\_\_\_\_ PLASTER \_\_\_\_\_ PIER FDTN. \_\_\_\_\_  
 TILE OR CONG. BLK. \_\_\_\_\_ DRYWALL \_\_\_\_\_ WALL FDTN. \_\_\_\_\_  
 CONG. SLAB \_\_\_\_\_ PANEL VEN. \_\_\_\_\_ SLAB FDTN. \_\_\_\_\_  
 STONE \_\_\_\_\_ UNFIN. \_\_\_\_\_ SINGLE SIDING \_\_\_\_\_  
 PIERS \_\_\_\_\_ DOUBLE SIDING \_\_\_\_\_  
 BASEMENT \_\_\_\_\_ PARTITION 8 1 2 3 \_\_\_\_\_ CONG. BLK. \_\_\_\_\_  
 NO. \_\_\_\_\_ NONE \_\_\_\_\_ BRICK \_\_\_\_\_  
 % \_\_\_\_\_ AVERAGE \_\_\_\_\_ CONG. FLR. \_\_\_\_\_  
 % \_\_\_\_\_ HEAVY \_\_\_\_\_ EARTH FLR. \_\_\_\_\_  
 % \_\_\_\_\_ EXT. WALLS \_\_\_\_\_ ROOF \_\_\_\_\_  
 SIDING ON SHEATHING \_\_\_\_\_ O.H. DOOR \_\_\_\_\_  
 SINGLE SIDING \_\_\_\_\_ FIN. INT. \_\_\_\_\_  
 WOOD SHINGLES \_\_\_\_\_ COMP. SHINGLES \_\_\_\_\_ ELECTRIC \_\_\_\_\_  
 ALUMINUM SIDING \_\_\_\_\_ STUCCO \_\_\_\_\_ PLUMBING \_\_\_\_\_  
 BRICK VENEER \_\_\_\_\_ STONE VENEER \_\_\_\_\_ OPENINGS \_\_\_\_\_  
 SOLID BRICK \_\_\_\_\_ CONG. BLOCK \_\_\_\_\_ CHIMNEYS \_\_\_\_\_  
 METAL PANEL \_\_\_\_\_ CLAPBOARD \_\_\_\_\_ HEAT - AIR COND. \_\_\_\_\_  
 HOT AIR FORCED \_\_\_\_\_  
 HOT AIR GRAVITY \_\_\_\_\_  
 HOT WATER OR VAPOR \_\_\_\_\_  
 FLOOR FURNACE \_\_\_\_\_  
 RADIANT \_\_\_\_\_  
 BASEBOARD \_\_\_\_\_  
 WALL UNITS \_\_\_\_\_  
 CENT'L. AIR COND. \_\_\_\_\_  
 NO HEATING \_\_\_\_\_

ROOFING \_\_\_\_\_ PLUMBING \_\_\_\_\_ REMODELING DATA \_\_\_\_\_ DETAIL \_\_\_\_\_ DATE \_\_\_\_\_ EST. COST \_\_\_\_\_ ADDED VALUE \_\_\_\_\_  
 TILE \_\_\_\_\_ ASPHALT \_\_\_\_\_ 4 FIXTURE BATH \_\_\_\_\_  
 SHAKES \_\_\_\_\_ ASBESTOS \_\_\_\_\_ 3 FIXTURE BATH \_\_\_\_\_  
 METAL \_\_\_\_\_ WOOD \_\_\_\_\_ 2 FIXTURE BATH \_\_\_\_\_  
 ROLL \_\_\_\_\_ SLATE \_\_\_\_\_ EXTRA WATER CLOSET \_\_\_\_\_  
 ATTIC & BSM'T. FINISH \_\_\_\_\_ WATER ONLY \_\_\_\_\_  
 A \_\_\_\_\_ % \_\_\_\_\_ F \_\_\_\_\_ NO PLUMBING \_\_\_\_\_  
 B \_\_\_\_\_ % \_\_\_\_\_ F \_\_\_\_\_ TILING \_\_\_\_\_  
 GAR. IN BSM'T. \_\_\_\_\_ BATH FLR. & WAIN. \_\_\_\_\_  
 1 CAR \_\_\_\_\_ 2 CAR \_\_\_\_\_ BATH FLR. & SHW. \_\_\_\_\_  
 FLOORS 8 1 2 3 \_\_\_\_\_ BATH FLOOR \_\_\_\_\_  
 EARTH \_\_\_\_\_ ROOMS \_\_\_\_\_  
 CONCRETE \_\_\_\_\_ 8 \_\_\_\_\_ 1 \_\_\_\_\_ 5 \_\_\_\_\_  
 PINE \_\_\_\_\_ 2 \_\_\_\_\_ 3 \_\_\_\_\_  
 HARDWOOD \_\_\_\_\_ VINYL TILE \_\_\_\_\_  
 POURED TOR. \_\_\_\_\_  
 CARPET/SUB. \_\_\_\_\_  
 INTERIOR \_\_\_\_\_  
 EXTERIOR \_\_\_\_\_  
 LAYOUT \_\_\_\_\_

REMODELING AND ADDITIONS \_\_\_\_\_  
 MEASURED BY \_\_\_\_\_  
 DATE \_\_\_\_\_  
 MEASURED BY \_\_\_\_\_  
 DATE \_\_\_\_\_  
 YR. UPDATED \_\_\_\_\_ LISTED BY \_\_\_\_\_ MEASURED BY \_\_\_\_\_ PRICED BY \_\_\_\_\_

TOTAL BLDG. VALUE \$ \_\_\_\_\_  
 BUILDING COMPUTATION  
 ITEM \_\_\_\_\_ AREA OR QUAN. \_\_\_\_\_ UNIT COST \_\_\_\_\_ TOTAL \_\_\_\_\_  
 F.B. 210 4.29  
 Partition 59 LF 18.90



TOTAL \_\_\_\_\_  
 FACTOR \_\_\_\_\_ %  
 REPLACEMENT VALUE \_\_\_\_\_  
 LAND VALUE \_\_\_\_\_  
 BUILDING VALUE \_\_\_\_\_  
 PROPERTY VAL. 100% \_\_\_\_\_  
 NOTES \_\_\_\_\_  
 PARCEL MAP FILE