


DATA NO.	MAP NO.	BLK. NO.	LOT NO.	FIELD BOOK	LAND VALUE	BLDG. VALUE	PURCH. PRICE	DATE
OCCUPANCY	TYPE & CONST.	SIZE	AREA	GRADE	AGE	EFF. AGE	COND.	REPL. VALUE
R-1	1 1/2 S FR	25 x 36	1560	BT	1948	66	RR	294136
Very Poor Condition								-80% X 65%
								23500
								19100

FOUNDATION	INTERIOR FINISH	OUTBUILDINGS	1	2	3	TOTAL BLDG. VALUE \$			
CONC. OR BRICK	PLASTER	PIER FDTN.				BUILDING COMPUTATION			
TILE OR CONC. BLK.	DRYWALL	WALL FDTN.				ITEM	AREA OR QUAN.	UNIT COST	TOTAL
CONC. SFAB	PANEL VEN.	SLAB FDTN.				1/2 STY	844	26.71	22543
STONE	UNFIN.	SINGLE SIDING							
PIERS		DOUBLE SIDING							
BASEMENT	PARTITION	CONC. BLK.							
NO. %	NONE	BRICK							
EXT. WALLS	AVERAGE	CONC. FLR.							
SIDING ON SHEATHING	HEAVY	EARTH FLR.							
SINGLE SIDING		ROOF							
WOOD SHINGLES		O.H. DOOR							
COMP. SHINGLES		FIN. INT.							
ALUMINUM SIDING		ELECTRIC							
STUCCO		PLUMBING							
BRICK VENEER		ATTACHED GARAGE							
STONE VENEER		STY. HGT.							
SOLID BRICK		BRICK VENEER							
CONC. BLOCK		FRAME							
METAL PANEL		FINISHED UP							
CLAPBOARD		LISTED BY							

INSULATION	ROOFING	PLUMBING	REMODELING DATA	DETAIL	DATE	EST. COST	ADDED VALUE	TOTAL
WALLS	CEIL.	FULL	4 FIXTURE BATH					22643
ROOF TYPE	GABLE		3 FIXTURE BATH					6793
MANSAARD	HIP		2 FIXTURE BATH					29436
GAMBREL	FLAT		EXTRA WATER CLOSET					11200
FLAT	EXPAN.		EXTRA SINK					79100
			WATER ONLY					30300
			NO PLUMBING					
			TILING					
			BATH FLR. & WAIN.					
			BATH FLR. & SHW.					
			BATH FLOOR					
			ROOMS					
			1					
			2					
			3					
			G					
			F					
			P					
			LAYOUT					



REMODELING DATA	DETAIL	DATE	EST. COST	ADDED VALUE	TOTAL	FACTOR	%	REPLACEMENT VALUE	LAND VALUE	BUILDING VALUE	PROPERTY VAL.	100%
KITCHEN					22643	20/10		6793	29436	79100	30300	
BATH												
HEATING - A.C.												
EXTERIOR												
ADDITION DATA	PURPOSE	DATE	EST. COST	ADDED VALUE								
PERMIT NO.	AMOUNT											
YR. UPDATED	LISTED BY	MEASURED BY	PRICED BY									
6/28/78	SCHON	MRS. PRINNE	ADDED 1-3 FIX BATH AND 1/4									

NOTES
 EXTREME FLY DAMAGE TO HOUSE IN REAR
 Renew-4-26-74
 House in need of much general repair & also damage to exterior walls (dep. 45%)