

DATA NO.	MAP NO.	BLK. NO.	LOT NO.	FIELD BOOK	LAND VALUE	BLDG. VALUE	PURCH. PRICE	DATE
OCCUPANCY	TYPE & CONST.	SIZE	AREA	GRADE	AGE	EFF. AGE	COND.	REPL. VALUE
			2226	3	1925		FAIR	27573
			190A					1300
								45
								30
								15
								16540
								785

FOUNDATION	INTERIOR FINISH	OUTBUILDINGS	1	2	3
CONC. OR BRICK	PLASTER	PIER EDTN.			
TILE OR CONC. BLK.	DRYWALL	WALL FDTN.			
CONC. SLAB	PANEL VEN.	SLAB FDTN.			
STONE	UNFIN.	SINGLE SIDING			
PIERS		DOUBLE SIDING			
		CONC. BLK.			
		BRICK			
		CONC. FLR.			
		EARTH FLR.			
		ROOF			
		O.H. DOOR			
		FIN. INT.			
		ELECTRIC			
		PLUMBING			

EXT. WALLS	KITCHEN EQUIP.	ATTACHED GARAGE
SIDING ON SHEATHING	NO.	STY. HGT.
SINGLE SIDING	NO.	BRICK VENEER
WOOD SHINGLES	NO.	FRAME
COMP. SHINGLES	NO.	FINISHED UP
ALUMINUM SIDING	NO.	LISTED BY
STUCCO	NO.	MEASURED BY
BRICK VENEER	NO.	DATE
STONE VENEER	NO.	
SOLID BRICK	NO.	
CONC. BLOCK	NO.	
METAL PANEL	NO.	
CLAPBOARD	NO.	

INSULATION	NO.	NO HEATING
WALLS	NO.	
CEIL.	NO.	
FULL	NO.	
ROOF TYPE	NO.	
MANSARD	NO.	
GABLE	NO.	
GAMBREL	NO.	
HIP	NO.	
FLAT	NO.	
EXPAN.	NO.	

ROOFING	NO.	PLUMBING
TILE	NO.	4 FIXTURE BATH
ASPHALT	NO.	3 FIXTURE BATH
SHAKES	NO.	2 FIXTURE BATH
ASBESTOS	NO.	EXTRA WATER CLOSET
METAL	NO.	EXTRA SINK
WOOD	NO.	WATER ONLY
SLATE	NO.	NO PLUMBING

TILING	NO.	REMODELING DATA
GAR. IN BSM'T.	NO.	REMODELING DATA
1 CAR	NO.	REMODELING DATA
2 CAR	NO.	REMODELING DATA
FLOORS	NO.	REMODELING DATA
B 1	NO.	REMODELING DATA
2 3	NO.	REMODELING DATA
EARTH	NO.	REMODELING DATA
CONCRETE	NO.	REMODELING DATA
PINE	NO.	REMODELING DATA
HARDWOOD	NO.	REMODELING DATA
VINYL TILE	NO.	REMODELING DATA
POURED TOR.	NO.	REMODELING DATA
CARPET/SUB.	NO.	REMODELING DATA

ROOMS	NO.	REMODELING DATA
B	NO.	REMODELING DATA
1	NO.	REMODELING DATA
3	NO.	REMODELING DATA
3	NO.	REMODELING DATA
G	NO.	REMODELING DATA
F	NO.	REMODELING DATA
P	NO.	REMODELING DATA
INTERIOR	NO.	REMODELING DATA
EXTERIOR	NO.	REMODELING DATA
LAYOUT	NO.	REMODELING DATA

YR. UPDATED	LISTED BY	MEASURED BY	PRICED BY
11-28-90	JT	Mrs. Souther	no change

ADDITION DATA	PERMIT NO.	AMOUNT	PURPOSE	DATE	EST. COST	ADDED VALUE

TOTAL	27573
FACTOR	15%
REPLACEMENT VALUE	27573
LAND VALUE	40000
BUILDING VALUE	17320
PROPERTY VAL. 100%	57320
	57400

NOTES	LAND - 2 HOMESITES
	20000 each
	MISPLACED IMPROVEMENT

